

FOSTCDRI-SM

Discontinuation Notice & RMA Guidance

Feb 11, 2009

Reason

A problem was discovered with the FOSTCDRI-SM causing low manufacturing yields. The problem was diagnosed as a flaw in the modulation scheme causing an undesirable interaction with some batches of the onboard fiber transceiver.

The modulation scheme has been revised accordingly. ***However, the revised modulation scheme is not backwards compatible.*** To avoid compatibility problems between the old and new revisions, model FOSTCDRI-SM has been discontinued. The replacement is model FOSTCDRI-SC.

RMA Guidance

For customers adding units to an existing system or requiring warranty repairs, B&B Electronics will perform a warranty upgrade of your FOSTCDRI-SM products to FOSTCDRI-SC. We will work with you to ensure this is accomplished in the least disruptive manner possible.